

Saskatchewan Health Authority

Public Water - Public Water Supply

Inspected by: Olamide Adebogun

Saskatchewan Health Authority
 (306) 446-6400
 101-11427 Railway Ave
 North Battleford SK S9A 3G8
 Canada

<p>Mail To: Resort Village of Kivimaa Moonlight Bay</p> <p>PO Box 120 Livelong SK S0M 1J0 CANADA</p> <p>Attention: Resort Village of Kivimaa Moonlight Bay</p> <p>Facility Inspected: Kivimaa Public Well, 010222 Resort Village of Kivimaa Moonlight Bay (306) 845-3336</p>	<p>Inspection Date: 20-Mar-2024 15:18</p> <p>Site Address: Kivimaa Drive Resort Village of Kivimaa Moonlight Bay SK S0M 1J0 Canada</p> <p>Phone Number: (306) 845-3336</p> <p>Fax Number: (306) 845-3686</p> <p>Email: rvkmb@myaccess.ca</p> <p>Violations: 0</p>
<p>Facility Type: Public Water, Public Water Supply</p> <p>Re-inspection Priority: Low</p> <p>Delivery Method: Email</p> <p>Certified Professionals:</p>	
<p>Inspection Type: Routine</p> <p>Inspection Reasons: Compliance</p>	

No = Not In Compliance N/O = Not Observed Yes = In Compliance N/A = Not Applicable

Water

- | | |
|---|-----|
| 1. Water Source | Yes |
| 2. Sampling | Yes |
| Water sample was last collected and submitted in January,2024. | |
| 3. Notification | Yes |
| 4. Treatment | Yes |
| The water is connected to UV light and two membrane filter. The bulb was observed with 32days remaining. | |
| Readings Taken: | |
| - 3:16 PM - Turbidity in By the tap in the pump house: 0.52mg/L | |
| 5. Treatment/Testing Equipment | N/A |
| 6. Storage & Handling of Chemicals | N/A |
| 7. Records | N/A |
| 8. Cleaning and Maintenance | Yes |

Actions Taken

Facility Contact: Resort Village of Kivimaa Moonlight Bay [7484]

Facility Address: Kivimaa Drive, Resort Village of Kivimaa Moonlight Bay SK S0M 1J0 Canada

Completed: 20-Mar-2024 15:18

Received By:



Amanda Bistlar

Inspector:



Olamide Adebogun, Public Health Inspector