

# Saskatchewan Health Authority

## Public Water - Public Water Supply

Inspected by: Stephen Clarke

Saskatchewan Health Authority  
(306) 446-6400  
101-11427 Railway Ave  
North Battleford SK S9A 3G8  
Canada

<b>Mail To:</b> Resort Village of Kivimaa Moonlight Bay  PO Box 120 Livelong SK S0M 1J0 CANADA <b>Attention:</b> Resort Village of Kivimaa Moonlight Bay  <b>Facility Inspected:</b> Kivimaa Public Well, 010222 Resort Village of Kivimaa Moonlight Bay (306) 845-3336	<b>Inspection Date:</b> 30-Aug-2021 12:30  <b>Site Address:</b> Kivimaa Drive Resort Village of Kivimaa Moonlight Bay SK S0M 1J0 Canada  <b>Phone Number:</b> (306) 845-3336 <b>Fax Number:</b> (306) 845-3686 <b>Email:</b> rvkmb@littleloon.ca <b>Violations:</b> 1
<b>Facility Type:</b> Public Water, Public Water Supply <b>Re-inspection Priority:</b> Low <b>Delivery Method:</b> Email <b>Certified Professionals:</b>	
<b>Inspection Type:</b> Routine <b>Inspection Reasons:</b> Compliance	
<b>Opening Comments and Observations:</b> Chris M. was present for this inspection. Jackie will be retiring as of this year, Dot Andrews will be the new administrator for this facility. 306-845-3336, rvkmb@myaccess.ca.	

No = Not In Compliance N/O = Not Observed Yes = In Compliance N/A = Not Applicable

### Water

- |  |     |
|--|-----|
| 1. Water Source  | Yes |
| 2. Sampling  | Yes |
| A sample sent in on 24 Aug 2021 sample was found to be ok. |     |
| 3. Notification  | Yes |
| 4. Treatment   | Yes |
| Readings Taken:<br>- 12:05 PM - Turbidity : 0.31mg/L       |     |
| 5. Treatment/Testing Equipment                             | N/A |
| 6. Storage & Handling of Chemicals                         | N/A |

**Facility Contact:** Resort Village of Kivimaa Moonlight Bay [7484]  
**Facility Address:** Kivimaa Drive, Resort Village of Kivimaa Moonlight Bay SK S0M 1J0 Canada  
**Completed:** 30-Aug-2021 12:30

---

7. Records Yes  
Please continue the recording of changed UV light bulbs and filters. The record on the wall of the wellhouse is adequate.
8. Cleaning and Maintenance No  
Please ensure regular cleaning of well house both where the water comes and the public area. Many spiders and webs filled with flies and other flying insects were noted on the walls, floors, ceiling, and on the equipment.  
Please ensure that all walls and wall to floor joints are made to be smooth, impervious, and easy to clean. In the event of a leakage, water may leak into the crevasse between the concrete floor and the wall.  
*- Facilities, as specified by the Public Health Inspector, are not kept clean and/or in good repair. Refer to clause 6(1)(b) of The Health Hazard Regulations.*
- 


**Actions Taken**

---

**Closing Comments:**


Inspection conducted and completed by Stephen Clarke, PHI.

**Received By:**



Resort Village of Kivimaa Moonlight Bay

**Inspector:**



Stephen Clarke, Public Health Officer